

JUANITA AVENUE

Subsurface Infiltration
System

Flow Meter

Surface Improvements
Pending Outreach

Pretreatment System

Actuated Valve

Diversion Pipe

Diversion Structure

DELANCEY AVE

